

How to calibrate a Cy-160 optical power meter

Article Overview

Calibrating a Cy-160 optical power meter involves using a traceable optical standard, matching the wavelength and connector type, and performing either absolute or relative calibration to ensure accurate readings.

Step-by-Step Calibration Procedure

1. Choose the Calibration Method

- o Absolute Calibration: Connect the Cy-160 to a traceable optical power standard, such as a calibrated laser or radiometer, and adjust the meter until its reading matches the reference value. This method provides the highest accuracy and traceability to national standards like NIST .

- o Relative Calibration: Use a previously calibrated optical power meter as a reference. Connect both meters to the same optical source and adjust the Cy-160 to match the reference meter's reading. This method is simpler but depends on the reference meter's accuracy .

2. Select the Appropriate Wavelength and Connector

- o Ensure the calibration source matches the wavelength(s) you intend to measure (commonly 850 nm, 1310 nm, or 1550 nm for fiber optics), .

- o Use the same fiber type and connector as in your measurements to minimize errors caused by reflections or connector mismatches .

3. Prepare the Calibration Setup

- o Use a stable optical source with minimal power fluctuations.

- o Ensure the Cy-160 and reference standard are properly warmed up and temperature-stabilized if required .

- o Minimize back-reflections by using low-reflectance connectors or angled physical contact (APC) connectors.

4. Perform the Calibration

- o Connect the Cy-160 to the optical source or transfer standard.

- o Record the meter reading and compare it to the reference value.

- o Adjust the Cy-160's internal calibration settings or apply a correction factor until the readings match the reference within the desired accuracy .

- o Repeat the process for all relevant wavelengths and power ranges.

5. Verify and Document

- o After calibration, verify the Cy-160 readings against the reference at multiple power levels.

- o Document the calibration results, including date, reference standard, wavelength, and any correction factors applied.

- o Maintain traceability to national or international standards for quality assurance .

6. Regular Recalibration

- o Optical power meters should be recalibrated periodically, depending on usage and manufacturer recommendations, to maintain accuracy over time . By following these steps, the Cy-160 optical power meter can achieve accurate, traceable measurements suitable for fiber optic testing and other precision applications.

How to calibrate a Cy-160 optical power meter

Introduction The RP460 Optical Power Meter is an ultra low cost, and compact power meter used for verifying both absolute and

In Calibrating Fiber Optic Instruments, I discussed calibrating fiber optic power meters, which measure optical power. This

#ftth #fiber #fiberoptic #powermeter How to calibrate a fiber optic power meter?

This optical power meter is widely used in the construction, maintenance, inspection and acceptance of optical fiber com-munication

Learn how to operate, maintain, and calibrate GAO Tek's Optical Power Meters with detailed guidelines for accurate fiber optic

Tribler, you know it's a good optical power meter for all of your needs and specs. When you need to diagnose and fix

primarily on these wavelengths. Other optical power meter users (e.g., compact-disc player manufacturers, users of erbium-doped

Hi We Are DealsonDiscount.com . we are a online fiber optic store . In this video we

View and Download THORLABS PM160T user manual online. USB and Bluetooth Optical Power Meter. PM160T measuring

View and Download THORLABS PM160 user manual online. USB and Bluetooth Optical Power Meter.

Here is the calibration over wavelength for a commercial fiber optic power meter. You can see the wavelength sensitivity of the

Calibration means that an instrument has been tested against a standard and set up to make measurements

Finally, the process of fiber optic power meter calibration is simple but vital. Using the common methods and tools

This guide covers when to calibrate, what calibration actually involves, what a legitimate certificate looks

An optical power meter is a professional testing device used to measure the power of optical signals accurately. It is

How to calibrate a Cy-160 optical power meter

There are some things to be careful of when you calibrate optical power meters. One common problem is zero point

Web: <https://millstraining.co.za>

